



CENTRADOR EN L PARA SENSOR CLS GAGE FOR SENSOR CLS

Material:

- ① CK60 - HRC: 50-55
- ② St37



Ejemplo de aplicación / Application example



A	L	L1	L2
120	120	55	70
120	150	55	70
124	180	105	120
124	250	105	120

How to order: CLS + L